Oil Field Environmental Incident Summary

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC
Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: HELLAND 15-19H

Field Name: RAY Well File #: 19510

Date Incident:4/8/2016Time Incident:12:30Facility ID Number:County:WILLIAMSTwp:157Rng:96Sec:19Qtr:

Location Description:

Submitted By: Alex Beach Received By:

Contact Person: Troy Brunsell

3015 16th Street SW, Suite 20

MINOT, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:0.4 MileDistance Nearest Water Well:0.4 Mile

Type of Incident: Fire

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No Units Recovered Units Spilled **Followup Units** Oil 1.2 Barrels 1.2 barrels 0 **Brine** Other 0

Description of Other Released Contaminant:

Inspected: Written Report Received: 5/4/2016 Clean Up Concluded: 4/29/2016

Risk Evaluation:

There are no immediate risks to report at this time. The fire had self-extinguished prior to the Reliability Operator's arrival.

Areal Extent:

1,198 sq. ft.

Potential Environmental Impacts:

There are no environmental impacts to report at this time. All of the released fluid remained on site.

Action Taken or Planned:

The impacted material will be cleaned up and disposed of. A root cause analysis will be performed.

Wastes Disposal Location: The recovered waste will be taken to an approved waste disposal facility.

Agencies Involved:

Updates

Date: 4/11/2016 Status: Reviewed - Assigned to Other Agency Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the fire was contained to the well pad. NDIC has oversight.